# Camshaft carrier removal and installation guide DV4 DV5 DV6

Reference : OM 4106



| | |
|---|---|
| **Item name** | Camshaft carrier removal and installation guide DV4 DV5 DV6 |
| **Bar code** | 3701555324234 |
| **Text** | Camshaft support alignment pins are required for timing chain replacement procedures on 1.4, 1.5 and 1.6 HDi engines.<br><br>Camshafts and timing chain are part of an assembly. To replace the camshaft timing chain, the assembly must be removed from the engine. This tool ensures correct positioning of the camshaft support during reassembly.<br><br>Suitable for all applications on 1.4 (DV4), 1.5 (DV5) and 1.6 (DV6) diesel engines. |
| **Engine codes** | DV5RD , YHY¤YH01 , YHY , YH01 , DV5RCF , YHT¤YH01 , YHT , DV5RC , YHZ , YHP , DV5RE , YHW , DV5RUC , YHV , DV5RUCD , YHR , DURATORQ , XUJH , ZTDA , Z2DA , ZTJE , XWGA , XWGB , XUGA , XVGA , XXGA , Z2GA , ZTGA , XVGB , LQJ¤YHY , D15DT , LQJ , LQP¤YHX , D15DTH , LQP , YHX , LQP¤YHS , D15DTH¤DV5RCE , DV5RCE , YHS , 5WZTV , 5WZHV |
| **OEM codes** | 0194-N (Citroën/Peugeot) , 11 9 870 (Mini) , 119870 , 194N , 2.000.022.900 (Fiat) , 2000022900 , 2190096 , 2190885 , 2302272 , 303-034 (Mazda) , 303-245 (Ford) , 303034 , 30324 , 3553732 , 3556998 , 9823954880 , 9826028980 , 9830146880 , 9830147280 , EN-52146 (Opel/Vauxhall) , EN52146 , MB996235 , MB996235 (Mitsubishi) , SU001A7967 , SU001A7988 , SU001B3237 , SU001B3238 , T9997170 , T9997170 (Volvo) |
| **Warranty period** | 2 years |

| | |
|---|---|
| **Vehicle type** | LV |
| **Fuel type** | Diesel |
| **Tariff code** | Tariff Normal (TN) |
| **Warranty Procedure** | EASY |




***Public price Exl. Tax : €34**

*Applicable user fees from 01/09/2026 to 31/08/2027

CLAS EQUIPEMENTS
83, chemin de la CROUZA
73800 CHIGNIN
France

Tel : +33 (0) 4 79 72 62 22
Fax :

Monday to Friday - From 8 to 12h and from 13h30 to 17h30 (16h30 on Friday)