
Timing tools Ford / Jaguar 2.0 - 2.2 - 2.4 Duratorq

Reference : OM 4230



Item name	Timing tools Ford / Jaguar 2.0 - 2.2 - 2.4 Duratorq
Bar code	3700461400926
Text	Allows fuel injection pump removal and replacement on Ford 2.0, 2.4 Duratorq Di/TDDi and 2.2, 2.4 Duratorq TDCi diesel engines. Also suitable for timing belt replacement on 1.4/1.6L engines used on Ford and PSA cars.
Contents	Contents: - alignment shaft for camshaft/crankshaft gear - chain tensioner - tool for removing the fuel pump cover - tool for locking the fuel injection pump gear The set includes the pins needed to lock the camshaft flywheel and align the crankshaft and fuel pump when checking the valve spring adjustment on 2.0- and 2.4-liter chain-driven engines.
Applications	Models : Citroën : Jumper Fiat : Ducato Ford : Focus, Mondéo, Transit, ranger Hyundai : Accent, Getz, I10, I20 Kia : Cerato, Picanto, Rio Land Rover: Defender Peugeot: Boxer

	Engines: 2.0 , 2.2 , 2.4 , 2.8 , 3.2 TDdi/TDCi/HDI For Engines built between 2002 and 2010
Engine codes	244DT , 4HU , 4HV , ABFA , D0FA , D2FA , D3FA , D4FA , D5BA , D6BA , F3FA , F4FA , FIFA , FMBA , FMBB , FXFA , H9FA , H9FB , HJBA , HJBB , HJBC , HJBE , JXFA , N7BA , N7BB , PHFA , PUMA 22 DT , QJBA , QJBB , QJBD , QJBS , SDBA , ZSD424 , DURATORQ , D2FB
OEM codes	11 3 290 , 11 32 90 , 113290 , 21-238A , 21-251 , 21234 , 21238A , 21251 , 21260 , 303-675 , 3031151 , 303675 , 303679A , 303681 , 303698 , 303732 , 49JE02018 , KM-6077 , KM6077 , T40011
Advice	Flywheel sprocket in place of the PMH sensor. Recommended for transverse engine.
Warranty period	5 years
Fuel type	Diesel
Tariff code	Tariff Normal (TN)
Product range	Approved by SNR
Warranty Procedure	EASY
Delivered in a case	YES
Insert size	1/3



CLAS EQUIPEMENTS
83, chemin de la CROUZA
73800 CHIGNIN
France

Tel : +33 (0) 4 79 72 62 22
Fax :

Monday to Friday - From 8 to 12h and from 13h30 to 17h30 (16h30 on Friday)