Bearing removal tool 2nd generation 2.1 Ø78mm

Reference : OM 3426



Item name	Bearing removal tool 2nd generation 2.1 Ø78mm
Bar code	3700461456879
Introduction	Essential tool for installing GEN 2 Ø78mm bearings. Second-generation wheel bearings come in the form of a wheel bearing+clip assembly. To avoid damage during installation, it is essential to use the appropriate tool.
Text	Time-saving: no shock absorber removal, no suspension arm removal, no camber adjustment on some vehicles.
Product highlight	Disassembly/mounting directly on the vehicle
Applications	Models : Ford: C-max, Focus Mazda: 3 Volvo : C 30, C 70, S 40, V 50
Engine codes	DURATEC , SHDA , HWDA , SHDC , HXDA , HXDB , SIDA , DURATORQ , G8DC , MTDA , G8DB , HHDA , QQDB , Q7DA , DURATORQ LYNX , KKDA , KKDB , SYDA , AODA , AODE , IXDA , G6DD , G6DB , G6DG , IQDB , IQDA , T3DA , T3DB , HWDB , G8DA , HHDB , CSDA , CSDB , QQDC , QQDA , AODB , G6DC , G6DE , G6DF , G6DA , ASDA , ASDB , G8DD , GPDA , HYDA , G8DE , G8DF , GPDC , JZDA , D4164T , B4164S3 , B4184S11 , B4184S8 , D4204T , B4204S3 , D5244T9 , D5244T8 , D5244T13 , B5244S4 , B5254T3 , B5254T7 , D4162T , D5204T5 , D5204T , B4204S4 , B5244S5 , D4204T2

Options	Hydraulic extractor OM9384 is suggested for highly seized bearings.
Warranty period	2 years
Tariff code	Tariff Normal (TN)
Warranty Procedure	EASY



CLAS EQUIPEMENTS
83, chemin de la CROUZA
73800 CHIGNIN
France

Tel : +33 (0) 4 79 72 62 22
Fax :

Monday to Friday - From 8 to 12h and from 13h30 to 17h30 (16h30 on Friday)