Single pulley stretch belt installation and removal tool

Reference : OM 4029



Item name	Single pulley stretch belt installation and removal tool
Bar code	3700461446979
Introduction	This tool is required for quick and convenient assembly and disassembly of the elastic V-belt (stretch) without damaging it. Designed for single-pulley engines.
Engine codes	939A6000 , 939A5000 , 939A3000 , 939A9000 , 199B6000 , 312A2000 , CXMA , CXXB , DEJA , CRBC , CRLB , CUNA , DCYA , DGCA , DJGA , CLHA , DBKA , CRKB , CRBD , CRLC , DADA , DPCA , DFGA , M47TUD20 , 204D4 , M57TU2D30 , 306D5 , M57D30 , 306D3 , M47TU2D20 , M57D25TU , 256D2 , 306D2 , M57TUD30 , 306D4 , N47D20A , N47D20C , VM98B , ENJ , VM07C , VM20C , VM48C , EB2ADT , HNP¤HN05 , HNP , HN05 , EB2ADTS , HNS¤HN05 , HNS , DV5RD , YHY¤YH01 , YHY , YH01 , DV5RCF , YHT¤YH01 , YHT , EB2¤EB2F , HMZ¤HM01 , HMZ , HM01 , EB2 , EB2F , EB2¤EB2D¤EB2F , HMT¤HM01 , HMT , EB2D , DV4TD , 8HX , 8HZ , DV6TED4 , 9HZ¤9H01 , 9HZ , 9H01 , DV4C , 8HR¤8H01 , 8HR , 8H01 , 8HP¤8H01 , 8HP , EB0 , ZMZ¤ZM01 , ZMZ , ZM01 , EB2DT , HNZ¤HN01 , HNZ , HN01 , EB2DTM , HNV¤HN04 , HNV , HN04 , EB2FB , HMP¤HM01 , HMP , EB2FAD , HMM¤HM05 , HMM , HM05 , EB2FA , HMR¤HM05 , HMR , EB2DTS , HNY¤HN02 , HNY , HN02 , DV5RCD , YHX , 9HY¤9H01 , 9HY , DV6TED4B , 9HV¤9H01 , 9HV , DV6ATED4 , 9HX¤9H02 , 9HX , 9H02 , EB2ADTDB , HNE¤HN05 , HNE , EB2ADTX , HNN¤HN07 , HNN , HN07 , EB2D¤EB2FD , HMU¤HM01 , HMU , EB2FD , EB2DTSD , HNX¤HN02 , HNX , HMY¤HM02 , HMY , HM02 , PUMA C , 4HG¤4H03 , 4HG , 4H03 , 4HH¤4H03 , 4HH , 4HJ¤4H03 , 4HJ , F30DT¤30DT , F1CE0481D , F30DT , 30DT , K7M_7 , K7M710 , K7M_8 , K7M800 , K7M718 , K7J_7

	, K7J710 , K7J714 , K7M818 , DV6FD , BHY¤BH02 , BHY , BH02 , EB2ADT¤EB2ADTD , HNK¤HN05 , HNK , EB2ADTD , 312A6000 , 312A4000 , 312A5000 , 188A9000 , 182B6000 , 199A2000 , 223A9000 , F1AE0481C , F1AE3481G , F1AE3481D , F1AE3481E , F1AGL411B , F1CE3481E , F1AGL4114 , F1AGL411D , F1AGL4113 , F1AGL411C , F1AGL4112 , F1AGL4111 , F1CFA401C , F1CFA401A , PUMA 22DT , 4HV , F1AE0481D , F1AE0481N , F1CE0441A , F1CE3481N , F1AGL411A , 199A9000 , 199A3000 , 312A7000 , 199B7000 , TU3A¤TU3AE5 , KFT¤KF01 , KFT , KF01 , TU3A , TU3AE5 , TU3A¤TU3JP , KFV , TU3JP , SPJE , SPJD , RTJC , IQJA , IQJC , DURATEC , SHDA , HWDA , SHDC , HXDA , HXDB , SIDA , QQDB , Q7DA , SYDA , AODA , AODE , IQDB , IQDA , MUDA , PNDA , ECOBOOST , JQDA , JQDB , XTDA , MUDD , PNDD , XTDB , HWDB , CSDA , CSDB , QQDA , AODB , L1T , L1V , M7JA , M7JB , FUJA , FUJB , FXJA , FXJB , FYJA , FYJB , A9JA , A9JB , STJA , STJB , SNJB , SNJA , ZETEC SE , SPJA , RTJA , RTJB , SPJC , U5JA , HXJA , RVJA , HXJB , STJC , STJD , SNJC , SNJD , RTJD , ZETEC S , FXDB , FXDD , ZETEC , FYDA , FYDC , FYDB , FYDD , FXDA , FXDC , FYDH , ASDA , ASDB , NGDA , NGDB , IQDC , FXJC , UTJA , DURATORQ , HJBA , HJBB , HJBC , HJBE , FMBA , N7BA , N7BB , D5BA , QJBC , QJBD , QJBA , QJBB , SDBA , RHBA , PNBA , HUBA , KGBA , HUWA , QVFA , SRFB , SRFA , QWFA , DRFF , CYFF , CVFF , F3FA , ABFA , D3FA , FIFA , CYFA , CYFB , PGFB , UHFB , UHFA , PGFA , DRFB , DRFA , P8FA , P8FB , SRFD , SRFE , SRFC , DRFC , DRFE , CYRA , CYFC , DRR5 , CYR5 , DRF5 , CYF5 , CVF5 , CYFG , CVR5 , USR6 , UYR6 , DRFG , G4LA , F1AFL411A , F1AGL411H , F1AFL411B , F1AGL411J , F1AGL411R , F1AFL411C , F1AGL411G , F1AGL411N , F1CFL411J , F1CFL411E , F1CFL411H , F1CFL411F , F1CFL411G , F1CGL411A , F1CFL411V , F1CE3481J , F1CGL411B , F1CFL411W , F1CGL411C , F1AGL411Y , F1AGL411U , F1AGL411X , F1CE3481C , F1CFL4117 , F1CFA401D , 182A4000 , 46341162 , 169A4000 , F6JA , ZJ , LF , PE , L8 , MZR , L8(DX) , BA¤LF(DX) , 646986 , 642992 , 642896 , 271951 , 642899 , 646980 , 646982 , 642990 , 642890 , LDC , B12XEL , D12XEL , HMH¤HM05 , HMH , LES¤HNZ , B12XHL , LES , LES¤HNP , D12XHL¤F12XHL , D12XHL , F12XHL , LEG , B12XHT , LEG¤HNS , D12XHT¤F12XHT , D12XHT , F12XHT , LEZ , B12XE , LEZ¤HMR , D12XE¤F12XE , D12XE , F12XE , HMX¤HM03 , HMX , HM03 , DV5RC , YHZ , DW10FC¤DW10FDCU , EHZ¤AH01 , EHZ , AH01 , DW10FC , DW10FDCU , 4HU , DV6E , 9HN¤9H06 , 9HN , 9H06 , DV6FE , BHW¤BH02 , BHW , DV6DTED , 9HP¤9H06 , 9HP , K7M750 , ANX , CFWA , CAYC , CAYB , CHYB , CLHB , CXXA , CKFC , CRMB , CUPA , DDYB , DFFA , CRLD , CHYA , CHYE , DTSB , DFHA , CHPA , DTUA , CFHF , CUUA , DFSA , CUUB , DFSB , CFHA , EP6FADTXD , 5GF¤5G06¤BNZ , 5GF , 5G06 , BNZ , CFHC , CAYD , DTRC , DTRE , BJK , CEBB , BJL , CECA , BJM , CECB , BJJ , CEBA , CKTC , CRVA , CYKB , DEJB , DCYB , DFGB , DDYA , CRKA , DFEA , CUAA , DDAA , DFCA , DCXA , DCZA , B4164S3 , B4184S11 , B4184S8 , B4204S3 , B4204S4 , D5244T10 , D5244T15 , D5244T21 , B5254T12 , D5204T7 , D5204T2 , D5204T3 , D5244T11 , B5204T8 , D5244T4 , D5244T5 , B5254T6 , B5254T8 , D5244T19 , D5244T14 , B5254T10 , B5254T11 , D5244T17 , D5244T12 , D5244T23 , B5204T9 , B4204T6 , D5244T16 , D5244T20 , D5244T22
Warranty period	5 years
Tariff code	Tariff Normal (TN)
Product range	Approved by SNR

Warranty Procedure EASY



***Public price Exl. Tax : €134**

*Applicable user fees from 01/09/2026 to 31/08/2027

CLAS EQUIPEMENTS
83, chemin de la CROUZA
73800 CHIGNIN
France

Tel : +33 (0) 4 79 72 62 22
Fax :

Monday to Friday - From 8 to 12h and from 13h30 to 17h30 (16h30 on Friday)