

Camshaft carrier removal and installation guide DV4 DV5 DV6

Reference : OM 4106



Item name	Camshaft carrier removal and installation guide DV4 DV5 DV6
Bar code	3701555324234
Text	<p>Camshaft support alignment pins are required for timing chain replacement procedures on 1.4, 1.5 and 1.6 HDi engines.</p> <p>Camshafts and timing chain are part of an assembly. To replace the camshaft timing chain, the assembly must be removed from the engine. This tool ensures correct positioning of the camshaft support during reassembly.</p> <p>Suitable for all applications on 1.4 (DV4), 1.5 (DV5) and 1.6 (DV6) diesel engines.</p>
OEM codes	0194-N (Citroën/Peugeot) , 2.000.022.900 (Fiat) , 303-245 (Ford) , 303-034 (Mazda) , 11 9 870 (Mini) , MB996235 (Mitsubishi) , EN-52146 (Opel/Vauxhall) , T9997170 (Volvo)
Warranty period	2 years
Vehicle type	LV
Fuel type	Diesel
Tariff code	Tariff Normal (TN)
Warranty Procedure	EASY



***Public price Exl. Tax : €34**

*Applicable user fees from 01/09/2025 to 31/08/2026

CLAS EQUIPEMENTS
83, chemin de la CROUZA
73800 CHIGNIN
France

Tel : +33 (0) 4 79 72 62 22
Fax :

Monday to Friday - From 8 to 12h
and from 13h30 to 17h30 (16h30 on
Friday)