

## **CO2 DETECTION KIT**

Reference: AC 3300



Item name CO2 DETECTION KIT

**EAN code** 3700461410413

**Text** 1- With the engine hot, take off the radiator cap or the expansion-tub cap and put-in the

indicated dose of the tracking fluid.

2- Put the bulb on the tube and squeeze it several times.

Any gas in the cooling system mixes with the tracking fluid.

The blue tracking fluid changes color (turns yellow) if there is an internal combustion

fault that forces CO2 into the cooling fluid.

Conclusion: problem with the cylinder head gasket.

**Specifications** - checks for gas combustion in the radiator

- the test fluid changes colour if a leak is detected

- fast identification of defective head gasket

Warranty period 2 years

Capacity (ml) 250.00 ml

**Capacity (1)** 0.25 1

**Tariff code** Tariff Normal (TN)

**Warranty Procedure EASY** 











\*Public price Exl. Tax : €146.00

\*Applicable user fees from 01/09/2023 to 31/08/2024

**CLAS EQUIPEMENTS** 83, chemin de la CROUZA 73800 CHIGNIN France

Tel: +33 (0) 4 79 72 62 22

Fax:

Monday to Friday - From 8 to 12h30 and from 14h to 17h30 (16h30 on Friday)