


Timing tools Ford / Jaguar 2.0 - 2.2 - 2.4 Duratorq

Reference : OM 4230



Item name	Timing tools Ford / Jaguar 2.0 - 2.2 - 2.4 Duratorq
Bar code	3700461400926
Text	Allows fuel injection pump removal and replacement on Ford 2.0, 2.4 Duratorq Di/TDDi and 2.2, 2.4 Duratorq TDCi diesel engines. Also suitable for timing belt replacement on 1.4/1.6L engines used on Ford and PSA cars.
Contents	Contents : <ul style="list-style-type: none">- camshaft/crankshaft sprocket alignment pin- chain tensioner- fuel pump cover removal tool- fuel injection pump pinion locking tool Includes the pins needed to lock the camshaft flywheel and align the crankshaft and fuel pump when checking valve timing on 2.0 and 2.4-liter chain-driven Engines.
Applications	Models : Citröen : Jumper Fiat : Ducato Ford : Focus, Mondéo, Transit, ranger Hyundai : Accent, Getz, I10, I20 Kia : Cerato, Picanto, Rio Land Rover: Defender Peugeot: Boxer Engines: 2.0 , 2.2 , 2.4 , 2.8 , 3.2 TDDi/TDCi/HDI

For Engines built between 2002 and 2010

Engine codes	PUMA 22 DT, 244DT , ABFA , D0FA , D2FA , D3FA , D4FA , D5BA , D6BA , F3FA , F4FA , F1FA , FMBA , FMBB , FXFA , H9FA , H9FB , HJBA , HJBB , HJBC , HJBE , JXFA , N7BA , N7BB , PHFA , QJBA , QJBB , QJBD , QJBS , SDBA , ZSD424 , 4HU , 4HV
OEM codes	303732 , 21260 , 49JE02018 , 303679A , 3031151 , 303698 , 21251 , 303681 , 303675 , 21234 , 21-251 , 303-675 , 21-238A , 11 3 290 , 11 32 90 , 113290 , KM-6077 , T40011
Advice	Flywheel sprocket in place of the PMH sensor. Recommended for transverse engine.
Warranty period	5 years
Fuel type	Diesel
Tariff code	Tariff Normal (TN)
Product range	Approved by SNR
Warranty Procedure	EASY
Delivered in a case	YES
Insert size	1/3



CLAS EQUIPEMENTS
83, chemin de la CROUZA
73800 CHIGNIN
France

Tel : +33 (0) 4 79 72 62 22
Fax :

Monday to Friday - From 8 to 12h
and from 13h30 to 17h30 (16h30 on
Friday)